BALTIMORE METROCENTER SURVEY

SURVEY NO.: B-2018

MAGI NO.: 0420185411 AREA: Cathedral Hill

Address: 18-20 East Franklin Street

Current Name: Maryland State Commission on Human Relations

Block: 552 Lot: 22-23 Lot size: 53 ft. x 140 ft. Materials: Brick and concrete Height: 3 Condition: Good Owner: East Franklin Partners Use: Commercial

Accessible: Yes, restricted Liber/Folio: CWM 4142/372

Historic Name: Date: ca. 1830 Architect/Builder: Style (if appropriate):

Designation:

Description: The original townhouses were united by a rusticated concrete facing on the first story and basement in the mid 20th century. The plain pilasters and single entablature of the doorways were replaced by a single modern glass and aluminum door; the other door became a blind window bay. Above the concrete facing, the six bays of the two houses are still intact, with gauged jack arches and modern plate glass windows. The common bond exterior brick may be a replacement of the original flemish bond. The cornice is relatively narrow, with two projecting brick courses below. The gable roof has a pedimented dormer with paired windows in each. The east elevation features a stepped gable. The addition of several windows in a five-bay regular pattern is an alteration of the early 20th century. A two-story rear addition facing St. Paul Place contains storefronts now used as offices by the Human Relations Commission.

Significance:

Area: architecture

Level: local

The main elements of architectural interest in the building are the stepped gable and dormers, which hint at the early 19th century origins of the structure. From 1911 until the early 1980's, the Consolidated Engineering Company had its headquarters at 18-20 East Franklin. The firm was one of several prolific construction companies in Baltimore in the early to mid 20th century and is still in business at 2 East Fayette Street.

Sources: DR 10-19-07, 1-25-13; Peale Museum Photo Coll.; city directories Surveyor and Date: Janet Davis, May 1985





18-20 East Franklin Street B-2018 Photo ca. 1945, Peale Museum

MC 6790



18-20 East Franklin Street B-2018
Cathedral Hill - Metrocenter Survey
Baltimore (City), Maryland
Photo: Janet Davis
Date: July 1984
Neg. loc.: Maryland Historical Trust

South elevation

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

Contract of						
1	NAME					
	HISTORIC					
	AND/OR COMMON					
	20 E. Franklin S	Street				
2	LOCATION				1/	
	STREET & NUMBER					
	20 E. Franklin S	Street				
	city.town Baltimore				CONGRESSIONAL DISTRICT	
-	STATE		VICINITY OF COUNTY			
	Maryland					
3	CLASSIFICAT	ION				
	CATEGORY	OWNERSHIP	STATUS	PRES	ENT USE	
	DISTRICTI	PUBLIC	XOCCUPIED	AGRICULTURE	_MUSEUM	
	X BUILDING(S)	PRIVATE	UNOCCUPIED	X COMMERCIAL	PARK	
	STRUCTUREI	вотн	_WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDENCE	
1	SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
	_OBJECTI	N PROCESS	XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC	
	_1	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	_TRANSPORTATION	
	5.7		_NO	MILITARY	_OTHER:	
	STREET & NUMBER	ineering Co., Inc.	4	Telephone #:		
	20 E. Franklin S	treet				
	CITY. TOWN Baltimore	_	VICINITY OF	Maryland 2120	ip code	
5	LOCATION O	F LEGAL DESCR	IPTION	Liber #: MLP 94	99	
	COURTHOUSE			Folio #: 157		
	REGISTRY OF DEEDS, ETC.	Records Office, Room 601		6/8/54		
	STREET & NUMBER	Baltimore City Courthouse				
	CITY, TOWN	Baltimore		STATE Maryland 2120)	
6	REPRESENTA	TION IN EXISTI	NG SURVEYS	nary tana 2120		
	M. School of a					
	City of Baltimor	e Neighborhood Sur	vey			
Ĭ	DATE 1975		FEDERAL	_STATE _COUNTY _XLOCAL		
	DEPOSITORY FOR		R HISTORICAL &		VOICE.	
	SURVEY RECORDS					
	CITY, TOWN	ARCHITECTURAL PRESERVATION				
_		Room 900	- Maria		12.2	
		26 South Calver	-10	i		
		Baltimore, Md. 2	1202	* £		

CONDITION

CHECK ONE

CHECK ONE

XEXCELLENT _GOOD

_FAIR

__DETERIORATED

RUINS

__RUINS __UNEXPOSED __UNALTERED

_ORIGINAL SITE

__MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This corner building was probably originally two 3½ story rowhouses. It has 6 bays, a sloped roof with two dormers and is surfaced in running bond brick. The first floor and basement are finished with concrete scored to imitate rusticated stone.

The entrance is the third bay from the right. The glass double doors and transom are framed by a molded door surrounded with a simple cornice. There are six stairs with a wrought iron railing. To the left of the entrance is a 3 sided projection at basement level with an iron railing. Between this platform and the entrance stairs are steps leading to the basement entrance. To the right of the main door are three basement windows, the one next to the stairs being blocked up. There are four windows on the first floor; the bay next to the entrance is a blind window.

There are 6 evenly spaced windows on the second and third floors with splayed brick lintels. Those on the second floor rest directly on the top edge of the rustication while those on the third floor have marble sills.

There are two pedimented dormers, each of which has 2 one-over-one double hung windows, and a chimney on the sloped roof.

The side wall on St. Paul Place features a stepped gable. There are five bays on the second through fourth floors and a central entrance flanked by 2 shop windows on the ground floor.

8 SIGNIFICANCE

PERIOD	AF	REAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	
PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	SCIENCE
_1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1700-1799	ART	ENGINEERING	_MUSIC	THEATER
<u>X</u> 1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
_1900-	COMMUNICATIONS	_INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
		_INVENTION		
SPECIFIC DAT	ES	BUILDER/ARCHITECT		

STATEMENT OF SIGNIFICANCE

See 10 E. Franklin Street

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY							
10 GEOGRAPHICAL DATA							
ACREAGE OF NOMINATED PROPERTY							
	es actions						
	\$ 5 W 5 5 4 W 5						
VERBAL BOUNDARY DESCRIPTION	3.0						
	£						
52'9" by 140'							
LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAR	PPING STATE OR COUNTY BOUNDARIES						
STATE COUNTY							
COUNTY							
STATE COUNTY							
III FORM PREPARED BY							
NAME / TITLE							
Marsha Rozansky, Planning Assistant							
ORGANIZATION DATE							
The Commission for Historical and Architectural	Preservation						
STREET & NUMBER	TELEPHONE						
26 S. Calvert Street, Room 900	396-4866						
CITY OR TOWN	STAYE						
Baltimore	Maryland 21202						

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.


The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust


The Shaw House, 21 State Circle


Annapolis, Maryland 21401

(301) 267-1438



B-2018 20 East Franklin Street Block 0552 Lot 022 Baltimore City Baltimore East Quad







Zo E. Franklin

B-2018

BIK